

NOV 04 2020



**Chevron U.S.A. Inc.**

NSPS 0000a Annual Report

For the Reporting Period 8/2/2019 to 8/1/2020

Mailing Address

Chevron U.S.A. Inc.  
c/o J. Austin Adams  
6301 Deauville Blvd  
Midland, Tx 79765

For questions and comments, please contact:

J. Austin Adams  
(432) 687-7852

[Jonathan.Adams@Chevron.com](mailto:Jonathan.Adams@Chevron.com)

Statement of Certification: Based on information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate and complete.

Name of Certifying Official: Mr. Brent Gros

Title: General Manager Operations

Signature of Certifying Official: Brent C Gros

Digitally signed by Brent C Gros  
Date: 2020.10.26 08:27:29 -0500

Signature Date: 10/26/2020



J. Austin Adams  
Environmental Specialist – Air

**MidContinent**  
**Chevron North America**  
6301 Deauville Blvd  
Midland, Tx 79706  
Tel (432) 687-7852  
Jonathan.Adams@Chevron.com

October 28, 2020

U.S. EPA Region 8  
ATTN: Director, Air and Toxics Technical Enforcement Program  
Office of Enforcement, Compliance and Environmental Justice  
1595 Wynkoop Street  
Denver, CO 80202-1129  
(303) 312-6312

RE: NSPS OOOOa Annual Report

As per 40 CFR §60.5420a(b), please find attached the Annual Report for Chevron's NSPS OOOOa affected sites. This report is for the compliance period of August 2, 2019 to August 1, 2020.

The COVID-19 pandemic has led to the need for electronic signatures as an alternative to authorizing the submission of this regulatory document. Once the COVID-19 pandemic has ended, Chevron will resume providing hard copies with original signatures.

If you have any questions concerning this submission, please contact me at (432) 687-7852 or by email at [jonathan.adams@chevron.com](mailto:jonathan.adams@chevron.com).

Sincerely,

A handwritten signature in blue ink, appearing to read "J. Austin Adams", with a stylized flourish at the end.

J. Austin Adams  
Environmental Specialist – Air

CC: Colorado Department of Public Health & Environment  
Air Pollution Control Division  
4300 Cherry Creek Drive South  
Denver, CO 80246

**The following facilities/wells are NSPS OOOOa Affected Facilities pursuant to 40 CFR § 60.5420a(b)**

Company Name	Facility Site Name	US Well ID	County	State	Latitude	Longitude
Chevron USA Inc	Central Processing Facility	N/A	Garfield	CO	39.57172	-108.34561
Chevron USA Inc	Skinner Ridge 25 BV	N/A	Garfield	CO	39.58650	-108.34044
Chevron USA Inc	Skinner Ridge 25CV	N/A	Garfield	CO	39.57847	-108.34128

**Fugitive Emission Components : Monitoring Survey Information**  
60.5420(b)(7)(i)-(v) LDAR Survey data for the collection of fugitive emission components.

Facility Name	Date of Survey	Begin Time of Survey	End Time of Survey	Operator Name	Ambient Temperature (F)	Sky Conditions	Wind Speed (mph)	Monitoring Instrument Used	Deviations From Monitoring Plan (If none, state none.) * (\$60.5420a(b)(7)(vii))
Central Processing Facility	9/26/2019	11:07 AM	12:28 PM	Crew 5 Colorado	65	Overcast	6	FLIR GFX320 #214	None
Skinner Ridge 25 BV	10/31/2019	10:34 AM	10:50 AM	Crew 5 Colorado	34	Overcast	4	FLIR GFX320 #214	None
Skinner Ridge 25 CV	10/31/2019	11:00 AM	11:06 AM	Crew 5 Colorado	34	Overcast	4	FLIR GFX320 #214	None
Central Processing Facility	1/16/2020	10:14 AM	11:33 AM	Crew 5 Colorado	36	Partly Cloudy	4	FLIR GFX320 #214	None
Central Processing Facility	4/23/2020	10:20 AM	11:22 AM	Crew 5 Colorado	52	Partly Cloudy	5	FLIR GFX320 #302	None
Skinner Ridge 25 BV	4/23/2020	12:15 PM	12:51 PM	Crew 5 Colorado	52	Partly Cloudy	5	FLIR GFX320 #214	None
Skinner Ridge 25 CV	4/23/2020	11:47 AM	11:59 AM	Crew 5 Colorado	52	Partly Cloudy	5	FLIR GFX320 #214	None
Central Processing Facility	7/30/2020	10:04 AM	11:04 AM	Crew 5 Colorado	88	Sunny	4	FLIR GFX320 #214	None

### Fugitive Emission Components: Leaking Component Data

Identification of Each Affected Facility (§60.5420a(b)(1))	Date of Survey (§60.5420a(b)(7)(i))	Date of Successful Repair of Fugitive Emissions Component *60.5420a(b)(7)(x))	Type of Component for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Number of Component for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Type of Component Not Repaired as Required in §60.5397a(h) * (§60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (§60.5420a(b)(7)(viii))	Type of Difficult-to-Monitor /Unsafe to Monitor Components Monitored * (§60.5420a(b)(7)(ix))	Instrument Used To Resurvey
No Leaking Component Data for this reporting Period								